

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problems Mailbox.**




Fig. 1






Fig. 2



2022-515866A





Fig.5

2025 RELEASE UNDER E.O. 14176



**Fig.6**

2022-5-28 00:00




Fig. 7




Fig. 8





Fig. 9





***Fig.10***




Fig. 11

2022-158660






Fig.12







Fig. 15



**Fig. 16**






Fig. 17A







COPIED FROM THE  
ORIGINAL FILED IN THE  
FBI RECORDS






Fig. 18C

170







Fig. 19A






**Fig. 20**



178



**Fig. 21A**




FIG. 21B





# HOME SENSOR UPPER





Fig.22



**Fig.23**




Fig. 24





Fig.25



**Fig.26**





Fig.27

194


FROM FIG. 27

TO FIG. 28B



LOWER MOTORS  
102-2, 4, 6, 8, 10, 12


MINI DRW 7 - 12 MOTORS



REVERSED OUTPUT  
CONNECTIONS FOR  
LOWER MOTORS

**Fig. 28A**

202205158660



**Fig.28B**






Fig. 29